








P12W



4xM4x0,7P Screw hole